



## **MASONITE COASTERS**

### **SUPPLIES NEEDED**

- **MASONITE COASTER**
- **EZ TRANS PAPER**
- **HEAT TAPE**

### **TEMP: 400, FIRM PRESSURE**

1. Print Image on Ez Trans paper.
2. Place in press masonite face up with transfer on top, using heat tape to secure transfer to masonite.
3. Use firm pressure, press for 35 – 40 seconds.
4. Remove from press, remove transfer and let cool.